Chidiebere Ochi-Okorie 3720 Bayou Circle Dickinson, TX 77539 Phone: 281-620-9050 Fax: 281-535-3553 RECEIVED CENTRAL FAX CENTER DEC 1 1 2004



To:	USPTO, Ramon M. Barrera	from:	Chidiebere Ochi-Okorie	
Faxc	703-872-9306	Dates	December 11, 2004	
Phone:	571-272-1987	Pages:	4, including cover	
Re:	Corrected Drawings			

New drawing and related amendment to the specification are presented in the following two pages in response to office action of 12/03/04.

Applicant Signature: Chreham ocundrum

December 11, 2004

Title of Invention: Automotive Ball System | App. #: 10/771,084 | Inventor: Chidiebere Ochi-Okorie


REPLACEMENT DRAWING SHEETS

One new drawing sheet is attached according to examiner's amendment and depicts an automotive disk (disk-shaped object) as FIG. 10. The automotive disk is equipped with several electromagnets, one of which is labeled 5.

FIG. 10



Title of Invention: Automotive Ball System Inventor: Chidiebere Ochi-Okorie App. #: 10,771,084



New Sheet

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:
☐ BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
☐ FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
COLOR OR BLACK AND WHITE PHOTOGRAPHS
☐ GRAY SCALE DOCUMENTS
☐ LINES OR MARKS ON ORIGINAL DOCUMENT
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
□ other:

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.